

LaCie RAID Manager Release Notes

Before updating LaCie RAID Manager, please take the following steps:

1. If you are using LaCie Desktop Manager, please download and install [the latest version](#) from LaCie support, as older versions of LaCie Desktop Manager may conflict with LaCie RAID Manager.
2. Update the device's firmware. Please see [the instructions in the User Manual](#).

To identify your current version of LaCie RAID Manager: Open the software. Select LaCie Storage Management, then select LaCie RAID Manager version.

To identify your device's firmware version: Open the LaCie RAID Manager. Select *Device*, then select your Adapter. There, select *Firmware version*.

To download the latest version of LaCie RAID Manager for Mac OS, [please click here](#).

To download the latest version of LaCie RAID Manager for Windows, [please click here](#).

HISTORY

Package 1061:

FW 2.0.3.1056

MAC driver: 1.0.3.0015

MAC LRM: 4.1.0.2060 (package 2061)

WIN driver: 1.1.3.1621 (WHQL)

WIN LRM: 4.1.0.2055

- [MAC] Update for compatibility with Mac OS 10.11 El Capitan
- [MAC] Driver fix for log timestamp incoherency
- [MAC] LRM package include new driver (functionally identical to 4.1.0.2060)

Package 1059:

FW 2.0.3.1056

MAC driver: 1.0.3.0014

MAC LRM: 4.1.0.2060

WIN driver: 1.1.3.1621 (WHQL)

WIN LRM: 4.1.0.2055

- Changes to mark, font, and format of messages in Mail Email Notify Setting
- [WIN] Fix to email setting failure with certain email providers
- [MAC] Fix to email setting failure when set up server 192.169.11.9

Package 1058:

FW 2.0.3.1056

MAC driver: 1.0.3.0014

MAC LRM: 4.1.0.2059

WIN driver: 1.1.3.1621 (WHQL)

WIN LRM: 4.1.0.2054

- Add Windows support
- Add Chrome browser support
- Enhance mail server configuration security
- [MAC] MacOS X Server support
- [MAC] Various minor fixes

Package 1056:

FW 2.0.3.1056

MAC driver: 1.0.3.0014

MAC LRM: 4.1.0.2056

- Improved default parameters management

Package 1055:

FW 2.0.3.1054

MAC driver: 1.0.3.0014

MAC LRM: 4.1.0.2054

- Fix unexpected alarms in LaCie RAID Manager log at device startup
- Fix log not refreshed in LaCie RAID Manager
- Fix temperature alert not visible in LaCie RAID Manager log
- Add Mac OS 10.10 (Yosemite) support
- Improve Firefox support
- Fix unexpected devices displayed in LaCie RAID Manager
- Other minor fixes

Package 1054:

FW 2.0.3.1054

MAC driver: 1.0.3.0014

MAC LRM: 4.1.0.2048

- Fix low performance with small files
- Fix rare case where product still ON at the end of offline RAID building
- Fix power button short press locking device
- Fix invalid fan and temperature events
- Improve log
- Other minor fixes

Package 1053:

FW 2.0.3.1053

MAC driver: 1.0.3.0012

MAC LRM: 4.1.0.2036

- Fix rare random drive disconnection
- Fix rare unexpected product shutdown
- Other minor fixes

Package 1049:

FW 2.0.3.1049

MAC driver: 1.0.3.0012

MAC LRM: 4.1.0.2036

- Improve low performance with small files
- Fix unexpected alerts when starting up device
- Fix LaCie RAID Manager not accessible when using an account without password
- Improved LaCie RAID Manager graphic user interface for Retina display
- Improved LaCie RAID Manager uninstallation process
- Other minor fixes

Package 1046:

FW 2.0.3.1045

MAC driver: 1.0.3.0013

MAC LRM: 4.1.0.2031

- Fix sleeping mode issue (product not detected when resuming from sleep mode)

Package 1045:

FW 2.0.3.1045

MAC driver: 1.0.3.0012

MAC LRM: 4.1.0.2031

- Improve "Foreground initialization" performance
- Fix "Identify" notification
- Fix user interface "buttons" refresh issue in LaCie RAID Manager
- Update help file
- Other minor fixes